



Notice of Lead-Based Paint Stabilization

| | |
|---|--|
| 1. Location: | Henry A. Brown School |
| 2. Project: | Lead-Based Paint Stabilization |
| 3. OEMS Contact: | Jennifer Donovan, Kelly Mayberry |
| 4. Email or Contact Number: | jdonovan2@philasd.org, kmayberry-ext@philasd.org |
| 5. Lead Inspector: | Acer |
| 6. Stabilization Contractor: | Delta |
| 7. Contractor Contact: | Bruce MacDonald |
| 8. Anticipated Start Date (MM/DD/YYYY): | 09/15/2025 |
| 9. Anticipated Completion Date (MM/DD/YYYY): | 09/15/2025 |
| 10. Brief Scope of Work Summary: | Stabilization of damaged lead-based paint. See table on next page for full scope of work. |

Scope of Work

| E l e m e n t | F l o o r | Space # | On-Site Room Name | Student/ Teacher Occupied (yes/no) | Component | Substrate Material | Paint Color | Description of Paint Damage | Paint Damage Quantity (sf) | XRF Reading (mg/cm2) | XRF (positive/ negative) |
|---------------------------------|-----------------------|---------|--------------------------------------|---|------------|-----------------------|-------------|--------------------------------|-------------------------------------|-------------------------|--------------------------------|
| 1 | 1 | 108B | Storage to Right of Cafetorium (103) | yes | Door Frame | Metal | Red | Flaking | 1 | 0.70 | Positive |
| 1 | 1 | 112 | Gymnasium | yes | Door Frame | Metal | Brown | Flaking | 1 | 0.70 | Positive |
| 1 | 2 | 206B | Left closet in Classroom 201 | yes | Pipe | Metal | Tan | Chipping | 1 | 0.70 | Positive |